

ESS weekly meeting (2022 W07)

A. Miyazaki et al



General planning: trouble shooting mode

FREIA Planning	2022-01-19			20	22													
					Ja	inua	iry		I	Febr	ruar	y		Ма	rch			Aŗ
Equipment	Responsible	e		3	10	17	24	31	7	14	21	28	7	14	21	28	4	11
		week	#	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
Liquefier & 2K pump	s Esat																	
RF power stations	Mykhailo																	
Cryomodule test sta	n Akira					C۱	107			C١	08			C۱	109			
							V	/e a	/ are	he	ere					3 to) fre		SS Or

- We found a leak in our flange connection between CM08 and VBox
- We will try to catch up the initial plan and try to be ready on W10

UNIVERSITET

W06 & W07 progress & W08 planning



wee	k						V	V06					
		M	NC	Т	UE		WED	-	THU	FR	I	SAT	SUN
date	5	07-	feb	08-	-feb		09-feb	10-feb		11-feb		12-feb	13-feb
		m	а	m	а	m	а	m	а	m	а		
previous CM	СМ07	departu	re to ESS		prepa	aring report		publis	sh report				
		coupler warm	n conditioning	Electrosy	ys tripped	coupler v	varm conditioning co	ntinued			N	2 cooling	
present CM	CM08	build concrete bun	e blocks on the iker	0	e valve to the al ones		ulation compressor; es in requifier	trouble shooting	purging		start liquifie	er to fill the Dewa	ar
next CM	СМ09	departure	from Orsay		transpo	ort from Orsay		arriv	al at UU	receptic	on test		

wee	k						W	/07		_			
		M	ON	٦	TUE		WED	THU		FF	RI	SAT	SUN
date	5	14-	feb	15	-feb		16-feb	17-feb		18-feb		19-feb	20-feb
		m	а	m	а	m	а	m	а	m	а		
present CM	CM08		leak between insulation vac and Lhe		ning up	l	eak test	reconne	ct crvolines	oupler onditioning	start LN2 cooling		
next CM	СМ09				reception test VNA								

We are here

weel	k						W	/08												
		M	N	Т	UE		WED	Т	ΉU	FR	1	SAT	SUN							
date	2	21-	feb	22-	-feb	23-feb		23-feb 24-feb 25-feb 26-feb 27-feb								24-feb		24-feb		27-feb
	-	m	а	m	а	m	ma ma ma													
present CM	CM08	LHe co	ooling	4K filling	coupler conditioning	2K pumping	RF calibration & interlock setup	C	CTS	MP conditioning	heat load	warm	ning up							
next CM	CM09						doorknot	mounting												
next next CM	СМ10				preparation at Orsay															
			Try to compensate the delay 3																	




CM09 reception tests



Verified by:

v1

CAV IN				Cal	oles veri	fication C	M09 at UU
File Trace/Chan Response Marker/Analysis Stimulus Utility Help		1		Socket asse	embly		V
Tr S11 LogM 0.100dB/ -0.40dB Tr 2 S12 LogM 5.000dB/ -6.0dB Tr 3 S21 LogM 5.000dB/ -96.0dB Tr 2 S12 LogM 0.002dB/ -96.0dB Tr 5 S21 LogM 5.000dB/ -96.0dB Tr 4 S22 LogM 0.002dB/ -36.3dB S15 SWR 100.0U/ -200U -	Print		Socket	name Sensor / Actuator type	PID name	Serial number	Electrical value ((before shippin
800.00 700.00 2 1: 351.579 MI 2: 351.439 MI Mir.4: 351.579 MI B' B'	Hz -0.05 dB Hz -35.04 dB W: 39.948 kHz Setup			Cemox Cemox Cemox	TT04 TT05 TT06	X138367 X133137 X133621	58,4 56,95 57,45
500.00 500.00 500.00 Cent	er: 35158 MHz G: 18909.8 ss: -85.040 dB Hz -84.79 dB to File			Cernox Cernox	TT07 TT08	X133178 X133616	57,45 58,5 54,9
500.00 400.00 400.00 400.00 400.00 400.00 400.00 400.00 400.00 400.00 400.00 400.00 400.00 400.00 400.00 400.00	W 98-717 kHz alt kg1.58 MHz Q: 9080.7 ss: -84.792 dB	LHe level	LC	01 Cemox PT 100 PT 100	TT09 TT10 TT11	X138366 PT 62 PT 57	58,7 106,25 106,2
300.00 7: 351.578.4	Hz -3.53 dB Hz 22.60			Cernox PT 100	TT12 TT20	X138368 PT 66	73,3 105,8
200.00		dauge does		PT 100 Cernox	TT21 TT22	PT 69 X138365	105,95 69,4
100.00			PT Co	upler PT 100	TT120 TT220	PTC31 PTC32	108 107
0.00	Print	gauge does not touch	LC	2 Heaters	EH01 EH02	EH08 EH09	82,5 84,2
-100.00	Colors Marker		200		EH10 EH20		83,9 82,5
1 >Ch1: Start 351.430 MHz St	op 351.680 MHz Functions	the ground	LC	Motor sensor a limit sensor	-		2.2 / 2.3 4,6
Cont. CH 1: S11 CA 2-Port	LCL		LU	Motor sensor	SM20		2.2 / 2.2




			ľ
ftor doliv	very @ UU		VACL
		Date	Time
		2022-02-10	14:50
Measured values (Ω)	C/NC	2022-02-11	09:00
		2022-02-14	08:45
2,8	С	2022-02-15	08:50
3,2	С	2022-02-16	09:00

Socket name	Sensor / Actuator type	PID name	Serial number	Electrical value (Ω) (before shipping)	C/NC
	Cernox	TT04	X138367	58,4	C
	Cernox	TT05	X133137	56,95	C
	Cernox	TT06	X133621	57,45	С
	Cernox	TT07	X133178	58,5	C
	Cernox	TT08	X133616	54,9	C
LC01	Cernox	TT09	X138366	58,7	С
LOUI	PT 100	TT10	PT 62	106,25	С
	PT 100	TT11	PT 57	106,2	С
	Cernox	TT12	X138368	73,3	С
	PT 100	TT20	PT 66	105,8	C
	PT 100	TT21	PT 69	105,95	С
	Cernox	TT22	X138365	69,4	С
PT Coupler	PT 100	TT120	PTC31	108	С
	11100	TT220	PTC32	107	С
		EH01	EH08	82,5	С
LC02	Heaters	EH02	EH09	84,2	C
LOUZ	i leaters	EH10		83,9	С
		EH20		82,5	C
	Motor sensor	SM10		2.2 / 2.3	C
LC03	a limit sensor	LS10		4,6	С
LCUS	Motor sensor	SM20		2.2 / 2.2	С
	a limit sensor	LS20		1,9	С
LC07	Liquid Helium	LT01	7343	367,75	С
	Level Sensor	LT02	7345	365,65	C
Socket name	Sensor / Actuator type	PID name	Serial number	Electrical value (µF) (before shipment)	C/NC
		PZ10		14,01	С
LC04	Actuators	PZ11		14,25	С
L004	ACIUAIOIS	PZ20		13,95	С
		PZ21		14,06	С


y @ UU		VACU	UM GAUGE OF CAVIT	<mark>Y STRING A</mark>	IT UU
/ @ 00	Date	Time	Pfeiffer TPG2020 (mbar	Limit	Name of controller
	2022-02-10	14:50	2,00E-03	1,00E-01	C. Svanberg
C/NC	2022-02-11	09:00	1,90E-03	1,00E-01	C. Svanberg
	2022-02-14	08:45	2,00E-03	1,00E-01	C. Svanberg
С	2022-02-15	08:50	2,10E-03	1,00E-01	C. Svanberg
С	2022-02-16	09:00	2,10E-03	1,00E-01	C. Svanberg






Part I: leak found in CM08 at cold





Kei


- Leak (1e-4 --1e-3 mbar) was observed in insulation vacuum
- The leak seems correlated to the bottom temperature and LHe level inside the cryomodule






helium signal by the leak detector (at cold)

Open the angle valve between the leak detector and insulation vacuum



After while Max leak 1e-3 mbar*L/sec



(He circuit 1100 mbar; 4K cooling phase)

 \rightarrow We decided to warm up the module





He circuit **30 mbar** insulation vacuum 1e-4 mbar



He circuit **1175 mbar** insulation vacuum 1e-4 mbar



Leak 1e-7 mbar*L/sec


Leak 1e-5 mbar*L/sec

Leak rate is smaller (1e-3 \rightarrow 1e-5 mbar*L/sec) than at cold but it is proportional to the differential pressure \rightarrow Leak exists also at warm



Where was the leak?






This is GHe exhaust → Thermal shrinkage happens at the very end of the cooling down process




Procedure: leak test before cooling down





Add leak detection phase








No impact to the planning (W08, 09, 10)

weel	k						V	/08					
		M	N	Т	UE	WED THU FRI SAT SI							
date	e	21-	feb	22-	feb		23-feb	24-feb		eb	26-feb	27-feb	
		m	а	m	а	m	а	m	m	а			
present CM	СМ08	LHe c	ooling	4K filling	coupler conditioning	2K pumping	RF calibration & interlock setup	MP conditioning	heat load	warn	iing up		
next CM	СМ09					doorknob mounting We might need to							
next next CM	CM10			preparation at Orsay work on Saturday									

wee	ek						N	V09					
		M	N	Т	UE		WED	F	ГНО	FR	I	SAT	SUN
dat	e	28-1	feb	01-	mar	(02-mar		8-mar	04-mar		05-mar	06-mar
		m	а	m	а	m	а	m	а	m	а		
previous	CN 400	warming up	completed /	disconnect		N	2 filling	outa	aing tast	out going test		waiting	in the box
CM	CM08	open the	e bunker	cryogenics	swap modules		2 111111g	outgo	oing test	outgon	ig test	waiting	III LITE DOX
present CM	СМ09				swap modules		ct cryogenics	connect va	acuum pumps		pum	ping vacuum	
next CM	СМ10				prepar	preparation at Orsay departure from Orsay transport						nsport	

wee	k						١	V10					
		MC	ON	Т	TUE WED					FRI		SAT	SUN
date	e	07-1	mar	08-	-mar	C	19-mar	10-mar		11-mar		12-mar	13-mar
		m	а	m	а	m	а	m	а	m	а		
previous CM	СМ08	waiting ir	n the box	departu	ire to ESS	prepa	ring report	publis	sh report				
present CM	СМ09				coupler w	arm conditionir	Ig			purging		N2 cooling	
next CM	СМ10		transport from Orsay					arriv	al at UU	receptio	on test		





Part II: TH595A in DB stations



DB-A 595A 907196 4800 hours with filament ON Since March 2020

- Few crowbar events happened from the beginning of the series CM tests (Nov 2020)
- Crowbar became more and more frequent over time (typically after May 2021)
- Crowbar became permanent without RF only with HV (Sep 2021)
- Crowbar logic was shared by the sections and we could not identify which one was first
- We first replaced 901204 in DB-B with a virgin new spare 912223
 - \rightarrow Crowbar in was still there but less frequent
- We also replaced 907196 in DB-A with a virgin new spare 916278
 - \rightarrow Crowbar in has never happened again

\rightarrow Conclusion: both were dead

DB-B 595A 901204 4800 hours with filament ON Since September 2019





901204 test @ FREIA outside the station

<u>Capacitance</u>

	THALES	This test
K-G1	117 pF	126.2 pF
G1-G2	246 pF	259.0 pF
G2-A	19 pF	23.2 pF


No problem

(constant off-set from our multimeter)

HV test at room temperature

	THALES*		This test	
	HV	current	HV	current
K+/G1-	2 kV	<1 uA	2 kV	0
G1+/G2-	1.5 kV	< 6 uA	1 kV	> 400 uA
G2+/A-	20 kV	12 uA	20 kV	0

*from TH595 755307 test report



<u>Conditioning</u>

Several cycles of applying HV in G1-G2 max 1.5 kV for 3 hours

- → Dark current in G1-G2 disappeared (<10 uA)</p>
- → The tube was sent back THALES





	THALES		
	ΗV	current	
K+/G1-	2 kV	<5 uA	
G1+/G2-	1.5 kV	< 5 uA	← THALES reproduced our
G2+/A-	35 kV	<10 uA	results after the conditioning

They forgot water cooling and destroyed the tube during the filament test

 \rightarrow No test with HV + filament ON + RF

Conclusion

- THALES reproduced our results after the conditioning
- We did not have a chance to check if the conditioning was also effective with filament ON + HV + RF
- The conditioning might just hide the issue only at cold
- \rightarrow Systematic and careful test is required




907196 test @ FREIA outside the station

Capacitance

	THALES	This test	
K-G1	128 pF	126.9 pF	
G1-G2	243 pF	244.9 pF	
G2-A	20.5 pF	22.5 pF	

No problem



HV test at room temperature

	THALES*		This test	
	HV	current	HV	current
K+/G1-	2 kV	<1 uA	800 V	0.5 uA
G1+/G2-	1.5 kV	< 6 uA	600 V	58.3 uA
G1-/G2+	-	-	800 V	0

*from TH595 755307 test report

- Polarity dependence observed
- Dark current slowly decreased with constant HV
- We stopped the test to avoid conditioning of this tube
- \rightarrow The tube still preserves the problematic status





- The FREIA lab team was glad to receive this clarification and their concerns are now clearer. It is our mutual conclusion, that there wasn't any issues with the returned tube ref. 901204:
 - FREIA applied a conditioning (hi-pot) on the tetrode which could explain that Thales doesn't identified any defect
 - Thales has observed no cracks on the ceramic and the coma stains disappeared after Thales cleaning. The stains are probably due to a metallic contact (maybe during the installation of the tetrode?)
 - Only one arc observed on the top of G2 grid, but the root cause is probably the crowbar firing (FREIA) or the disjunction on the equipment failure (Thales). This arc root cause is not due to a potential tetrode defect
 - FREIA said that a second tetrode have the same kind of issue. Freia will test the tetrode (HV insulation test) and will send the results to Thales. A discussion will be conducted (Thales/FREIA) and the decision will be discussed concerning a potential treatment (conditioning)
 - The report was sent to THALES on Feb 4th 2022 but they have not answered yet
 - My suggestion is to check everything as much as we can at FREIA before transportation to THALES and add more witnesses (from ESS)
- We have not applied extensive conditioning yet because it might just hide the issues at cold
- However, we could also perform the conditioning and mount the tube back to DB station and see what happens
 - If the crowbar issue does not happen, this conditioning can be a solution
- \rightarrow We need a strategical decision making among ESS, THALES, and FREIA