


CM10 motor LN2 test report

N. Gandolfo - 01/12/2022

Introduction



VSS32 Motor with elongated shaft


Configuration reminder :

- Production tuner with CM10 motor
 - Had firstly completely failed, only at low temperature, during the LHe qualification of cryomodule CM10 at Uppsala
 - Similar to CM3 test (replacement, and reparation of the motor)
 - Works always well at room temperature (but not tested at full torque)
 - Had previously failed twice in a row, even after rising the current from 0.6 to 1.0 A
 - Equipped with its copper collar
 - Equipped with elongated shaft
- Production tuner with prototype motor
 - Never failed in any configuration/project thus never extensively tested
 - Assembling variations already known : bearing adjustment, bearing coating

Goal: Observe any variation by adding elongated shaft that could confirm gearbox shaft misalignment theory proposed during previous meeting.

Day 1

1. Very first attempts failed
2. Then it started to move properly
3. And then quickly started to get stuck more and more
4. Finally stuck again




...we were about to warm-up and change the configuration, we tested to rise the current to 1.0 A, and the motor finally seemed to work very properly !!

Day 1

...we were about to warm-up and change the configuration, we tested to rise the current to 1.0 A, and the motor finally seemed to work very properly !!

Non linearity issue due to proximity from home position. OK, not a concern. (proto motor only)

Offset due to wrong initialization, not a concern.




Day 2

- Large stroke testing (1.0 A), round trip


➔ No issue

➔ Hysteresis on CM10 motor tuner mostly imputed to mechanical slight issue, sometimes observed on some tuner testing. Not motor related.




Day 3

- Single way to 5,120 rev (1.0 A)
- ➔ No issue, good correlation with round trip of the day before







Day 2 round trip



Day 3 single way

Day 3

- Evaluation of motor start current from 1.0 A down to 0.32 A → OK (!!)
- Stress test 10,000 motor rev. (input of gearbox, not output), at 0.4 A → OK (!!)







Y axis :
Strain gage
output of
dummy
cavity

Thermal
instabilities due
to LN2 refilling

Day 4

- Again, stress test 10,000 motor rev. (input of gearbox, not output), at 0.4 A → OK




Y axis :
Strain gage
output of
dummy
cavity

Day 5

- Again, stress test 10,000 motor rev. (input of gearbox, not output), at 0.4 A → **NOK (1)**
- Put tuner at 2,560 rev (1.0 A) → **OK**
- Evaluation of motor start current from 1.0 A down to 0.32 A → **OK (!!)**
- Again, stress test 10,000 motor rev. (input of gearbox, not output), at 0.4 A → **NOK (2)**

Carefull, Y scale is larger than previous slides



Also, prototype motor is full OK

Overview

- Day 1 – Monday
 - Stuck at the very beginning, then work for a while until lost of steps
 - Loss of steps, more and more at half-nominal current (0.6 A)
 - Motor works if the current is pushed to 1.0 A (driver limit)
- Day 2 – Tuesday
 - Large tuner stroke measurement at 1.0 A (0 → 5,120 rev) → **Passed** (max stroke : 5,888 rev)
- Day 3 – Wednesday
 - Put tuner at 5,120 rev position using 1.0 A → **Passed**
 - Start current motor measurement : **0.32 A**
 - Stress test at 0.4 A : 10,000 rev around the max position → **Passed**
- Day 4 – Thursday
 - Stress test again → **Passed**
- Day 5 – Friday
 - Stress test again → **Failed**
 - Recovery by pushing the current again to 1.0 A → **Ok**
 - Moving to lower position (2,560 rev) at 1.0 A → **Ok**
 - Start current motor measurement : **0.32 A**
 - Stress test again at 0.4 A → **Failed after few successful cycles**
- Day 6 – Monday
 - Quick trials, motor seems ok to work only if current is pushed (0.8 A / 1.0 A tested)

Conclusions

- Elongated shaft seems to have improved the motor behavior (previous attempts of current rising always failed at LT)
- Still, this system is not sufficient to fully recover the motor presumably damaged since cryomodule qualification
- Performances have been temporarily restored even at very low current (0.32 A around max position)

Next steps :

- Test without copper collar to identify any performance variation (W.49)
- Stress test with fresh motors w/ and w/o elongated shaft (W.50/51)

Further more :

- Test of old CM3 failed motor (which was repaired by Phytron early this year)
- Test of 2nd batch motor (2019 procurement vs 2017, clearly not the same play on output shaft)
- Internal inspection, coating wear evaluation, dimensional measurement around front bearings)

Full explanation tentative of the root cause (to be consolidated) :

Motor issue observed on LHe cryomodules qualification (at least CM10 and CM3, after having solved the driver current issue) might be explained by the addition of 2 causes :

1. **Misalignment of shaft : Allows high contact mechanical stress of internal pinions of planetary gearbox due to mechanical interference of the teeth.**
2. **Weak pinions coating : ADLC (amorphous carbon) appears to have a limited lifetime in vacuum, which can be strongly reduced depending of mechanical contact pressure. This also seems antagonist with MoS₂ / Ws₂ coating where friction rate (and then wear rate) drops when high contact pressure are applied**

Both causes participated to quick degradation of the coating while maintaining a steel on steel high pressure contact leading to galling issue (friction coefficient super high). At room temperature (but possibly especially at 1 bar), the steel on steel interface is less an issue.