
1. Visual inspection from TL012 upper bellow into VB


There does not seem to be anything in contact with this line...




2. Visual inspection from TL012 upper bellow into VCS 💙

- No copper shield on this part
- Cannot see past the G10 separator (camera does not fit)

- **3.** Distance measurement from CF flange to bellow flange
- 45 mm displacement towards VB wrt drawing












4. Blow hot air (ca. 50C) through bayonnet and let air out after TL016 outlet in VB (see graph next page)

- Pumping circuit at ca. 330 K
- Other LHe circuit at ca. 300 K
- Thermal shield TTs at ca. 300 K
- Did not see any hot spot on the joints where the bayonet meets the TL


VB, VCS and TL012 NOT under vacuum








VB, VCS and TL012 NOT under vacuum




5. Visual inspection from TL012 lower bellow into VB



- Lines are separated thanks to the spacer, but
- Between the spacer and the bayonnet
 - One seems to be in contact with the copper shield
 - They are round each other, not sure if in contact





- 6. Visual inspection from TL012 lower bellow into VCS
- SCHe line touches a bit the thermal shield
- Both Lhe lines are touching LN2 lines

























7. Blow hot air (ca. 50C) through bayonnet and let air out after TL016 outlet in VB (see graph next page)

- Pumping circuit at 347 K
- Other LHe circuit at 303 K
- 4K tank at 297 K
- LN2 shield TTs at 300 K
- LN2 piping at 301 K

VB, VCS and TL012 UNDER vacuum

Stopped after a few hours. Did not want to leave the hot air running through the night.

VB, VCS and TL012 UNDER vacuum



OUTCOME of TESTS

- Visual inspection:
 - Lines inside TL012 are round each other and some times in contact with either other lines or the copper shield
 - The copper shield is only present in some places and the LN2 line is in contact with it and with no MLI
 - The lines at either side of the TL are too long, except for the pumping line (moved upwards 45 mm)
- T profile
 - Increase in temperature in LHe piping in contact with TL016 might be normal from conduction point of view.
 - Increase in temperature in any part of the thermal shield or the LN2 piping is not normal.

